Fire Safety Division
Fire Department

BUILDING INSPECTION / COMPLAINT FORM

City of Rochester

Public Safety Building
Civic Center Plaza - 3rd Floor
Rochester, New York 14614
(716) **428-7037**

COMPANY E12

INSPECTION # 99 - 08540

ADDRESS: VAN BERGH AV | FROM / TO: 104 | TAX ACCT #

PROPERTY OWNER | ADDRESS | PHONE 000-0000

CITY | STATE | ZIP

MAILING NAME | ADDRESS | PHONE

CITY | STATE | ZIP

EMERGENCY CONTACT | ADDRESS | PHONE 000-0000

CITY | STATE | ZIP

NFPA 901 CODES	GENERAL PROPERTY USE	SPECIFIC PROPERTY USE	STRUCTURE TYPE	STRUCTURE STATUS

NO ENTRY DATES:

BUSINESS NAME | PHONE
BUSINESS OWNER
ADDRESS
PHONE
BUSINESS EMERGENCY
ADDRESS
PHONE

SPECIAL INSTRUCTIONS:

SPECIAL HARZARDS OR CONSTRUCTION

A = ATTIC
C = CELLAR
G = GARAGE
O = OUTSIDE
# = FLOOR #

DIRECTION ROOM #, ETC.	COMPLAINT	DISPOSITION by FIRE SAFETY: REFERRED	ORDERS ISSUED	CORRECTED	NOT REQUIRED
	☐ NO VIOLATIONS NOTED AT THIS TIME				
	Single family dwelling				
Y N					
☐ ☐	SPRINKLER SYSTEM				
☐ ☐	COOKING HOOD SYSTEM				
☐ ☐	FIRE ALARM SYSTEM				
☐ ☐	STANDPIPE SYSTEM				
☐ ☐	COOKING SYSTEM				
☐ ☐	BARS/WIRE ON WINDOWS				

OFFICER PREPARING REPORT:	COMPANY	DISTRICT	GROUP	DATE
	02	3	2	8/26/99
BUS/PROP REPRESENTATIVE:	POSITION / TITLE			DATE OF REINSPECTION
FIRE SAFETY INSPECTOR:				DATE

RFD 501 REV. 12/97

COPY TO FIRE SAFETY

259576

T&C chimney
103 Koladyne Ave
Gates N.Y. 14606
436-3996 429-5543

Customer Johnson
Address 104 Lanburgh
City Rochester State NY Zip 14610
Phone 288-3259
Date 1-16-99 Time 11:30

CONDITION REPORT



	Satisfactory	Unsatisfactory	Not Applicable
CHIMNEY			
1. Height	✓		
2. Chimney Cap/Spark Arrestor	✓		
3. Crown / Wash	✓		
4. Brickwork / Mortar	✓		
5. Flashing	✓		
6. Flue Tiles	✓		
7. Moisture Resistance	✓		
FIREPLACE			
8. Smoke Chamber	✓		
9. Damper	✓		
10. Firebox / Grate	✓		
11. Ash Container	✓		
12. Spark Screen / Doors	✓		
13. Tools / Gloves	✓		
14. Hearth Protection	✓		
15. Misc.:			
WOODSTOVE OR FIREPLACE INSERT			
16. Stovepipe Condition (woodstove)			
17. NFPA Approved Flue Connection (insert)			
18. Installation / Thimble / Clearances			
OTHER SAFETY CONSIDERATIONS			
19. Fire Ext. / Smoke Detectors / CO Alarms			
20. Gas/Oil Furnace Flue Liner	✓		
21. Fire Escape Plan			

Note: This sheet is the result of a visual inspection done at the time of cleaning. It is intended as a convenience to our customer, not as certification of fire worthiness or safety. Since conditions of use and hidden construction defects are beyond our control, we make no warranty of the safety or function of any appliance and none is to be implied.

- Type of Fireplace: ☐ Pre-fab ☒ Masonry ☐ Modular
- No. of Stories: 1 (2) 3 4 • No. of Fireplaces: (1) 2 3 4
- Woodstove: ☐ Insert ☐ Free Standing ☐ Pellet
- Type of Wood Used: ☐ Soft ☒ Hard ☐ Wet ☐ Dry
- Last Cleaned: 4+.5 Year(s) Ago ☐ Never
- Number of cords burned per season: _____
- Flue Size: ☐ 8"×8" ☒ 8"×13" ☐ 13"×13" ☐ 8"×17" ☐ 13"×17" ☐ 8" Round ☐ 6" Round ☐ _____
- Outside Chimney Dimensions: _____" × _____"
- Fireplace Opening Size: _____" × _____"
- How did you hear about us? ☐ Referral ☒ Yellow Pages ☐ Media–TV, Newspaper ☐ Direct Mail ☐ Other

COMMENTS:

The fireplace appears to have no extensive damage done by the Chimney fire. The flu tiles still have minor glazing. but a little hotter fires to reduce glazing. Have fireplace inspected going into each burning season.
Fireplace fashions 1936 Hudson Ave 266-8967
• woodstove •

CUSTOMER VERIFICATION

I have read this form and now understand which areas of my woodburning system appear to be satisfactory and which areas are not satisfactory.

Signed X Lawrence E. Johnson Date 1-16-99

NEXT SERVICING RECOMMENDED

on 1 (month) 16 (day) 00, 00 (year)

The fireplace and chimney should be inspected yearly for any structural faults.

Sweep's or Mason's Signature [signature]

RECEIPT / INVOICE

DESCRIPTION		PRICE
Chimney Cleaning		55.00
FILE		
	SUBTOTAL	55.00
		4.40
DATE COMPLETED 1-16-99	TOTAL	59.40

© 1994 Copperfield Chimney Supply, Inc.

WARNING

The use of this device is a violation of the fire prevention code of the City of Rochester for the reason/s checked below:

X Repairs Needed

____ No Permit

____ Violation Not Corrected

____ Other _____

_____

Any use of this device until this seal is removed is subject to penalty under section 54-24 of the Fire Prevention Code.

B/C. A. Pecoraro
Inspector

12/29/98
Date

ROCHESTER, NEW YORK FIRE DEPARTMENT FIELD INCIDENT REPORT

239716

ALARM

A | INCIDENT # 98238 83 | BOX # | NODE # 14006 | ADDRESS NUMBER 184 | STREET Vanbergh | TYPE AV | DIR.

DATE MO 12 DA 29 YR 98 | DAY OF WEEK 3 | WEATHER COND 3 | TEMP 5 | ALARM TYPE 1 | GOV'T BLDG

TIMES

FIRST ALARM
TIME OF ALARM 1841 | CODE 9 ENGINE 1843 | CODE 9 TRUCK 1846 | UNDER CONTROL | CODE 2 TIME 1909

EXTRA UNITS SENT
TIME OF ALARM | CODE 9 ENGINE | CODE 9 TRUCK | TIME OF ALARM | CODE 9 ENGINE | CODE 9 TRUCK

SECOND ALARM
TIME OF ALARM | CODE 9 ENGINE | CODE 9 TRUCK | AMBULANCE CODE 9 | B/C CODE 9 1847

RESPONSE

FIRST ALARM

UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R
E12	W	D04	W	MD4	W	BC3	W						

EXTRA UNITS SENT

UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R

MULTIPLE ALARM

UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R
UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R	UNIT	W/R

DESCRIPTION OF FIRE

INC TYPE 53 | TYPE CONST | STORIES | SPECIFIC PROPERY USE | MOBILE PROP TYPE | AREA OF ORG. | EQUIP INV | FORM OF HEAT IGN | FORM MAT'L | TYPE MATL | IGN FACTOR | CODE 5 | STRUC DMG | DRUG RELATED

YEAR | MAKE | MODEL | LICENSE NUMBER | SERIAL NUMBER | VOLTAGE

FIRE EXTENDED TO | EXT OF FLAME DMG

REFERRAL TO PROPERTY CONSERVATION
DATE JAN 4 1999

OWNER/OCCUPANT

OWNER/ INITIALS L | NAME Johnson | OCCUPANT INITIALS L | NAME Johnson

OWNER ADDRESS NUMBER | STREET | TYPE | DIR | CITY | STATE | ZIP

FILE

COMBAT

NUMBER USED BOOST | 1 1/2" | 1 3/4" | 2 1/2" | 3" | M.S. | OXY | PORT ABLE | FOAM | AMOUNT OF WATER USED | SPKLR | STAND PIPE | HYD PRESS | HYD COND | SMOKE DET | ENTRY

AFTERMATH

DOLLAR LOSS OF PROPERTY | NUMBER OF RESCUES | INJURED CIV. F.F. | DEAD CIV. F.F. | REFERRED TO: FIRE SAFETY | FIRE INVESTIGATION

REMARKS smoke in house due to defective damper in fireplace. Emptied fire box, opened damper and red tagged fireplace

RANK BC | INIT 3 | NAME Pecorara | GRP CPY 1 | BATT BC33 | SIGNED: S. Pecorara

RFD 101 REV. 12/91